

Engineering Technical Order

Date: September 26, 2011

RPG Procedures to Support Dual Polarization, Software Note 81

This document provides instructions to update RDA HCI files, RDA Help files, and Combined EPSS files on the RPG to support implementation of Dual Polarization on the RDA. This document also provides instructions to temporarily disconnect certain data lines during the installation of Dual Polarization. These data lines will be re-connected in coordination with the ROC following System Acceptance.

To view this modification document click on the link below or copy and past the URL in your web browser.

http://www.roc.noaa.gov/SSB/SYSDOC/TECHMAN/SUBS/DISCLAIMER_IFRAME.ASP?FILENAME=SOFT81FNL.PDF